

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1056
ENE
> 1
1.393 mi.
7354 ft.

RESIDENCE
2453 EAST 13TH STREET
BROOKLYN, NY

NY Spills S117535249
N/A

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name: RESIDENCE
Address: 2453 EAST 13TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1410874 / 2015-02-17
Facility ID: 1410874
Facility Type: ER
DER Facility ID: 459476
Site ID: 504597
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2015-02-12
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2015-02-12
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported

Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2015-02-12
Spill Record Last Update: 2015-02-17
Spiller Name: RAZWAN MIRZA
Spiller Company: PROPERTY OWNER
Spiller Address: Not reported
Spiller Company: 999
Contact Name: SALMA
DEC Memo: "02/12/15-Hiralkumar Patel. alternate address: none no PBS or other spills found. 6:11 PM:- spoke with Mr. Mirza, property owner. he mentioned that the oil he collected in empty container during boiler cleanout, got spilled onto basement floor. oil spilled onto concrete surface. there is no drains in affected area. he confirmed no petroleum odors outside boiler room. he will cleanup the spill and send document/pics. Razwan Mirza **property owner** 2453 East 13th Street Brooklyn, NY 11235 PH. (917) 476-5640 email: mirzar@hra.nyc.gov 02/17/15-Hiralkumar Patel. received email from Mr. Mirza (at 4:45 PM on 02/13/15) including pics. he mentioned that oil collected in empty bucket, while clearing out air lock in boiler, spilled around boiler. oil spilled onto basement floor which is mostly covered with ceramic tiles. area around boiler is solid thick concrete foundation. spill was cleaned up. case closed."

Remarks: "unsure total amount spilled; spilled onto concrete floor and dirt floor. cleanup is pending home owner; customer refused cleanup service from provider"

All Materials:
Site ID:

504597

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 1253943
Operable Unit: 01
Material ID: 2256325
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported